

Work Order Bid (ID)

WORK TO BE PERFORMED IN ACCORDANCE WITH 2011 TENNESSEE WEATHERIZATION FIELD GUIDE and ANY LOCAL CODES. QUESTIONS SHOULD BE DIRECTED TO EAST TENNESSEE RESOURCE AGENCY -WEATHERIZATION DEPT.

WORK ORDER INFORMATION

Work Order Name: WO/60006EA7142/1 Work Order Type: Weatherization Audit Name: 60006EA7142

CLIENT INFORMATION

Client ID: 60006EA7142

AGENCY INFORMATION

Agency: East Tennessee Human Resource Agency Agency Phone: (865) 691-2551 Address: 9111 Cross Park Drive, Suite D100 Fax: (865) 531-7216

> Knoxville, TN 37923 Email Address:

Agency Contact: Alexander, Randy Work Phone:

Cell Phone: (865) 705-8545

Email Address: Ralexander@ethra.org

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Pre: 1580 Post:1300 Year built: 2000

Type of structure: site built

Client ID: 60006EA7142

Approx. SF: 875

Measures

Client ID: 60006EA7142

Measure 1 Infilt	ration Redctn			Componen	ts			Inspected
Comment Pre: 158 Post 130 1) Seal p		n sink: tota	al of 3 i	oipes: appro	x. 1LF of	clear		
caulk. 2) Clear 3) Vacuu 4) Repla	caulk interior door frame um and Mastic 7 Supply ace 8 Ln. Ft. of 6" supply tine has several holes. F	es @ D1 & duct boots duct line (& D2 (; and 1 @ Kitch	34 LF) Return nen with Flex	k Duct			
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous Su	Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 2 DWF	I Tank Insulation			Componen	ts			Inspected
Measure 2 DWF	I Tank Insulation			Componen Estimated			Actual	Inspected
Measure 2 DWH Comment # Material / Labor	Description / Comment	Units	Qty	•		Qty		Inspected Total
Measure 2 DWH Comment # Material / Labor		<i>Units</i> Each		Estimated	1	Qty	Actual	
Measure 2 DWH Comment # Material / Labor	Description / Comment		Qty	Estimated	1	Qty	Actual	
Measure 2 DWF Comment # Material / Labor 1 Hot Water Equipm	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
Measure 2 DWF Comment # Material / Labor 1 Hot Water Equipm 2 Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Oty	Actual	
Measure 2 DWF Comment # Material / Labor 1 Hot Water Equipm 2 Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
Measure 2 DWF Comment # Material / Labor 1 Hot Water Equipm 2 Labor	Description / Comment DHW Tank Insulation	Each	Qty 1 1	Estimated	1		Actual	

	Measure 3 DWF	l Pipe Insulation			Componen	ts		ı	Inspected	
C	comment 6 Ln. Ft.	@ Each Hot and Cold \	Water Line	9						
				Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	DHW Pipe Insulation	Each	1						
2	Labor	DHW Pipe Insulation	Each	1						
C	Other Detail									
				Measur	e Sub Total:		,	Sub Total:		
	Field Notes:									
	<i>Measure</i> 4 Floo	r Ins. R-19			Componen	te F1			Inspected	
			D 11 fibor	alaaa k	•		davin			
C		al cost: Remove current oor condition. Install R-19		•		-		ı		
	•	e: on 24" OC.	o insorgiac	o batte	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	. joioto ai	о орон	'		
					Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	875						
2	Labor	Floor Insulation -	SqFt	875						
		Fiberglass Batts - R-19								
3	Miscellaneous Su	Added Misc Cost	Each	1						
C	Other Detail									
				Measur	e Sub Total:		,	Sub Total:		
ſ	Field Notes:									

Client ID: 60006EA7142

cap, insul * Material / Labor Insulation ! Labor	I Cost is to add Attic Addate lid to R30, and instance of the R30 and instance	•		•	·	energ	y Actual Unit Cost	Total
Insulation Labor	Attic Insulation - Blown Cellulose - R-38		_			Qty		Total
Insulation Labor	Attic Insulation - Blown Cellulose - R-38		_	Unit Cost	Total	Qty	Unit Cost	Total
Labor	Cellulose - R-38	SqFt	875					
	Attic Inculation Plans							
	Attic Insulation - Blown Cellulose - R-38	SqFt	875					
Miscellaneous Su	Added Misc Cost	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
the gas pa SN: IR630 Owner sta last 2 yea	ates that she uses porta ac is not working. 01ADAAF499911273 ates that heating system ars. end servicing HVAC gas	n has bee	n broke	en and out o	f service	for the)	
repair.				Estimated	,		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipmen	Furnace Tuneup	Each	1					
Labor	Furnace Tuneup	Each	1					
Other Detail								
Other Detail								
Other Detail			Measur	e Sub Total:			Sub Total:	

Client ID: 60006EA7142

Measure 1 Henri	gerator Rplcmnt			Componen	its		I	nspecte		
Comment 18 C. F.	Energy Star									
			Estimated				Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
0 Refrigerators	Energy Star - Any	Each	1							
Other Detail										
			Measur	e Sub Total:]	Sub Total:			
Field Notes:						-				
Measure 8 CO N	Monitor is Needed			Componen	its		ı	nspecte		
	Monitor is Needed O detector in hallway clo	se to bedi	rooms.	-	its		I	nspecte		
		ose to bedi	rooms.	-			I Actual	Inspecte		
Comment Install Co		ose to bedi <i>Units</i>	ooms.	-		Qty		Total		
Comment Install Co	O detector in hallway clo			Estimated	<u> </u>	Qty	Actual			
Comment Install Co Material / Labor Health and Safety	O detector in hallway clo	Units	Qty	Estimated	<u> </u>	Oty .	Actual			
Comment Install Comment Material / Labor Health and Safety Labor	O detector in hallway clo **Description / Comment** CO monitor	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual			
Comment Install Co Material / Labor Health and Safety	O detector in hallway clo **Description / Comment** CO monitor	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Oty	Actual			
Comment Install Comment Material / Labor Health and Safety Labor	O detector in hallway clo **Description / Comment** CO monitor	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual			
Comment Install Comment Material / Labor Health and Safety Labor	O detector in hallway clo **Description / Comment** CO monitor	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual			
Comment Install Comment # Material / Labor 1 Health and Safety 2 Labor	O detector in hallway clo **Description / Comment** CO monitor	Units Each Each	Qty 1 1	Estimated	<u> </u>		Actual			
Comment Install Comment # Material / Labor 1 Health and Safety 2 Labor	O detector in hallway clo **Description / Comment** CO monitor	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost			
Comment Install Comment Install Comment # Material / Labor 1 Health and Safety 2 Labor Other Detail	O detector in hallway clo **Description / Comment** CO monitor	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost			
Comment Install Comment Install Comment # Material / Labor 1 Health and Safety 2 Labor Other Detail	O detector in hallway clo **Description / Comment** CO monitor	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost			

Measure 9 Fix I	mproper Venting (Clot	thes Dryer))	Componen	ts		ı	Inspected
Comment 3 Ft Flex	x + 8 Ft. Stiff Duct with [Damper to I	Exterio	r				
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
] []		
			Meacur	e Sub Total:] []	Sub Total:	
Field Notes:			INICASUI	e Sub Total.]		
Measure 10 Pres	sureRelief Piping Nee	ded		Componen				Inspected
				Estimated	· 		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Pressure relief piping	Each	1					
2 Labor	Labor	Each	1					
Other Detail						1		
] []		
			Measur	e Sub Total:]]	Sub Total:	
Field Notes:				L				
		Work Or	der Gra	nd Total:		Gran	d Total:	